



A Case Study
Bulldozer Strength





Client's Testimonial

We put the E50 down on a low/wet section of dirt road at the range with no prep and it sat there for weeks being driven over and getting kind of pushed into the dirt/mud. We did the test without any further prep to see what effect tracked/military vehicles might have on a lonely EcoGrid road in the middle of nowhere. The bulldozer driver asked several times if I really wanted him to do this. He was quite surprised (and relieved - you know how the General is about looks) as he knew how the machine tore up the rest of that road when he had to turn around.

I've included a before and after photo. From the before you can see there are ruts, so the E50 wasn't even flat when we started the test. We could not have made it any nastier. The after shows a brown patch where we had just done another test with a backhoe with bucket full of stone that sat in one place and ground the front wheel back and forth with big knobby tires that caught and twisted the cells. The cosmetic damage is from both tests combined. All the nicks and splits are above the dirt line, so filling the cells is a big deal for long term use. It will still be there at the range for many years to come!

